



TEAM TIP

Release Date: October 11, 2018

SLI

Communication #: T-18-10-01

Model Year(s): 2015-2019

— Confidential and Proprietary —

VERSION: R01 (October 11, 2018)

IMPORTANT

If you are working with a printed copy, please verify you have the most current version of these instructions.

SUBJECT: HOOD ALIGNMENT

PURPOSE

This Team Tip is designed to bring awareness to updated information regarding hood alignment for all 2015-2019 Slingshot models. Updated information has been added to the Service Manual to provide dealers with clear direction on how to properly adjust hood latches, cable release timing and gap alignment using commercially available tools.

AFFECTED MODELS

MODEL YEAR	MODELS
2015–2019	Slingshot S / SL / SLR / GT

SERVICE MANUAL PROCEDURES

If a Slingshot vehicle is exhibiting erratic hood latch release / engagement, or the gap between the rear of the hood and cowl panel is not even, refer to the Service Manual for the most up-to-date adjustment procedures. **Reference the BODY / FRAME chapter > BODY COMPONENT INSTALLATION** for the updated information to help properly address these concerns:

- Hood Latch Cable Adjustment
- Hood Alignment

IMPORTANT UPDATES INCLUDE

- Left and right hand hood cables should be adjusted simultaneously for optimum performance.
- Front hood latch timing must be set before setting rear hood latch timing.
- Always check hood latch operation following hood alignment adjustment.