



TEAM TIP

Release Date: October 25, 2018

IND

Communication #: I-18-10-01

Model Year(s): 2015-2019

— Confidential and Proprietary —

VERSION: R01 (October 25, 2018)

IMPORTANT

If you are working with a printed copy, please verify you have the most current version of these instructions.

SUBJECT: NEW DIGITAL WRENCH FUNCTIONALITY FOR SCOUT MODELS

AFFECTED MODELS

MODEL YEAR	MODELS
2015–2019	Scout / Sixty / Bobber

PURPOSE / INFORMATION

Digital Wrench update version 09/13/2018 and later now **REQUIRES** an internet connection to perform ECM Reprogramming on Scout/Scout Sixty/Scout Bobber motorcycles. The new Reconfiguration Procedure automatically confirms vehicle information accuracy during ECM reprogramming.

IMPORTANT

If internet is unavailable on the computer running Digital Wrench, ECM Reprogramming cannot be performed.

When connecting to Digital Wrench, if you try to connect to a Scout / Scout Sixty / Scout Bobber motorcycle and Digital Wrench shows *Wrong Vehicle Selected*, execute the new ECM Reprogramming / Reconfiguration operation under the Special Tests menu. After completion, Digital Wrench should now show the vehicle as Connected.



The information contained within this document is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Industries. This document is provided for the sole use of authorized Polaris dealers and distributors. This document is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Industries Inc.