

Measure no.

US 64275931-01

Subject

Changed key location at PDI for K51

Status date (mm/dd/yy)

6/13/18

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

6/13/18

Created by

Simon Stammeler

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K51

Engine**Body****Production period (from/to)**

(mm/dd/yy)

6/13/18 /

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

Complaint

During the pre-delivery check, the ignition key is not found on the number plate carrier

Cause

There was a change in the process steps at the Berlin factory.

Measure

The ignition key will be in the storage compartment as of production date 13/06/2018 (see photo)

Complaint

	Fault location	Fault type	Fault place
↳	51/25 Ignition key	Positioning fault	

Cause

	#	Fault location	Fault type	Fault place
↳	1	66/12 Radio-operated key, Keyless Ride		
		Repair Task	Special Clearance	Area

No

Electrics/Electronics

Fault code

Progman / DIS / ISTA / ISTA/P

System

State

Version

© 2002-2018 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.

