

Service Bulletin

Service Bulletin - Technisches Rundschreiben - Circulaire Technique - Circular Tecnica

Date: 29 January 2018

Subject: Rear wheel rim

Product: **Brutale 800 Dragster RR**

This Service Bulletin cancels and replaces the previous No. 203.

Compared to the previous communication, the following variation has been introduced: information for the identification of a compliant wheel.

NOTIFICATION OF RECALL:

A non conforming rear wheel rim has been used on some motorcycles which may therefore potentially fail during normal use of the vehicle thereby increasing the risk of a fall.

IDENTIFICATION OF VEHICLES POTENTIALLY CONTAINING THE DEFECT:

The present recall involves 211 vehicles produced from 26 June to 25 September 2017 that may be equipped with the defective rear wheel rim.

Please refer to the attached list for involved models and chassis numbers.

DESCRIPTION OF THE DEFECT:

On some motorcycles subject to the current recall the rear wheel rim is potentially non conformant and is therefore subject to malfunction.

In the interest of our customer's safety, and as regulated by law, you may sell but not deliver to customers before having completed the below described "**Recall Procedure**".

NOTIFICATION TO CUSTOMERS:

MV Agusta will notify all registered owners about this recall, inviting them to bring the motorcycle to their dealer. An example customer letter is attached.

To protect the safety of our riders, it is our mutual responsibility to ensure the recall service is performed on all affected motorcycles. In addition, we strongly urge you to perform the recall service even if the motorcycle was not purchased from your dealership.

You are also required to perform the recall service on all affected models in your dealership inventory prior to delivering, renting or leasing those vehicles.

If you are not sure that a safety recall has been completed on a particular motorcycle, please contact MV Agusta Customer Service via e-mail (MVAgusta.AfterSales@mvgusta.com).

IMPORTANT NOTICE

We request that you contact any owners of affected models that your records show as unregistered. Inform them of the safety recall and make arrangements to remedy the defect on their motorcycle as soon as possible. We also require that you activate their registration thereby enabling us to send the owner's letters via direct mail, as required by the law.

RECALL PROCEDURE

Check the frame number (VIN) of your bike. If included within the list attached to this Circular, proceed with the Warranty Claim as specified in the next steps.

WARRANTY CLAIM:

- Send Warranty Claim to activate the spare parts order and subsequent reimbursement of the spare part and labour. In addition to the vehicle's information, provide the following details:
 - Type of warranty = 2 available options:
 - New in stock motorcycles = **GX**
 - Sold motorcycles with activated warranty = **GS**
 - Special warranty number = 2813 (to be used both for **GX** and **GS**)
 - Qty 1 component code = 3 available options:
 - Code 80C0C0046 black rim / gold hub and nipples;
 - Code 80A0C0046 black rim / red hub and nipples;
 - Code 8000C0046 white rim / red hub and nipples.
 - Operation code: N 099
 - Labour: 0.8 ore
 - Defect code: 099
 - Incident date: enter warranty request date

- Take the new rear wheel received and identified with green stamp / dot and / or the "R17" stamp on the rear hub as in the following pictures:



- Install the new rim while respecting the specifications in the workshop manual.
- Run a dynamic test of the motorcycle to verify its conformity.
- Package the non compliant rear wheel rim previously removed and contact MV Agusta Spare Parts: Ms. Emanuela Bottelier (emanuela.bottelier@mvagusta.com) or Mr. Filippo Macalli (filippo.macalli@mvagusta.com) to organize the component's return to MV Agusta.
- Complete the Warranty Request Procedure by entering the repair date.

NOTE: We would like to remind you that, according to the new functional and warranty management procedures, it will be necessary to complete the operation request with the repair completion date in order to proceed with the correct warranty reimbursement (see technical note n° 004). In addition, until the non conformant part is received, reimbursement of the entered warranty will not be possible.

Thank you in advance for your cooperation. We remain at your disposal should you require further technical support.

Best regards,

MV AGUSTA MOTOR S.p.A.
Technical Service Department
Recall 2813

Attachments:

- 1 - List of all motorcycles involved in SAFETY RECALL 2813.
- 2 - Facsimile letter for MV Agusta motorcycles owners.

List of all motorcycles involved in SAFETY RECALL 2813

ZCGB322BBHV012955	ZCGPFGNU6HV014053	ZCGB322BBHV020044	ZCGB322BBJV020104
ZCGB322BBHV013011	ZCGPFGNU8HV014054	ZCGB322BBHV020045	ZCGB322BBJV020105
ZCGB322BBHV013013	ZCGPFGNUXHV014055	ZCGB322BBHV020046	ZCGB322BBJV020106
ZCGB322BBHV013023	ZCGPFGNU1HV014056	ZCGB322BBHV020047	ZCGB322BBJV020107
ZCGB322BBHV013024	ZCGPFGNU3HV014057	ZCGB322BBHV020048	ZCGB322BBJV020108
ZCGB322BBHV013025	ZCGPFGNU5HV014058	ZCGB322BBHV020049	ZCGB322BBJV020109
ZCGB322BBHV013038	ZCGPFGNU7HV014059	ZCGB322BBHV020050	ZCGB322BBJV020110
ZCGB322BBHV013045	ZCGPFGNU3HV014060	ZCGB322BBHV020051	ZCGB322BBJV020111
ZCGB322BBHV013102	ZCGPFGNU5HV014061	ZCGB322BBHV020052	ZCGB322BBJV020112
ZCGB322BBHV013103	ZCGPFGNU7HV014062	ZCGB322BBHV020053	ZCGB322BBJV020113
ZCGB322BBHV013244	ZCGPFGNU9HV014063	ZCGB322BBHV020054	ZCGB322BBJV020114
ZCGB322BBHV013352	ZCGPFGNU0HV014064	ZCGB322BBHV020055	ZCGB322BBJV020115
ZCGB322BBHV013394	ZCGPFGNU2HV014065	ZCGB322BBHV020056	ZCGB322BBJV020116
ZCGPFGNU6HV014005	ZCGPFGNU4HV014066	ZCGB322BBHV020057	ZCGB322BBJV020117
ZCGPFGNU8HV014006	ZCGPFGNU6HV014067	ZCGB322BBHV020058	ZCGB322BBJV020118
ZCGPFGNUXHV014007	ZCGB322BBHV020004	ZCGB322BBHV020060	ZCGB322BBJV020119
ZCGPFGNU1HV014008	ZCGB322BBHV020005	ZCGB322BBHV020061	ZCGB322BBJV020120
ZCGPFGNU3HV014009	ZCGB322BBHV020006	ZCGB322BBHV020062	ZCGB322BBJV020121
ZCGPFGNUXHV014010	ZCGB322BBHV020007	ZCGB322BBHV020063	ZCGB322BBJV020122
ZCGPFGNU1HV014011	ZCGB322BBHV020008	ZCGB322BBHV020064	ZCGB322BBJV020123
ZCGPFGNU3HV014012	ZCGB322BBHV020009	ZCGB322BBHV020065	ZCGB322BBJV020124
ZCGPFGNU5HV014013	ZCGB322BBHV020010	ZCGB322BBHV020066	ZCGB322BBJV020125
ZCGPFGNU7HV014014	ZCGB322BBHV020011	ZCGB322BBHV020067	ZCGB322BBJV020126
ZCGB322BBHV014015	ZCGB322BBHV020012	ZCGB322BBHV020068	ZCGB322BBJV020127
ZCGPFGNU8HV014023	ZCGB322BBHV020013	ZCGB322BBHV020069	ZCGB322BBJV020128
ZCGPFGNUXHV014024	ZCGB322BBHV020014	ZCGB322BBHV020070	ZCGB322BBJV020129
ZCGPFGNU1HV014025	ZCGB322BBHV020015	ZCGB322BBHV020071	ZCGB322BBJV020130
ZCGPFGNU3HV014026	ZCGB322BBHV020016	ZCGB322BBHV020072	ZCGB322BBJV020131
ZCGPFGNU5HV014027	ZCGB322BBHV020017	ZCGB322BBHV020073	ZCGB322BBJV020132
ZCGPFGNU7HV014028	ZCGB322BBHV020018	ZCGB322BBHV020074	ZCGB322BBJV020133
ZCGPFGNU9HV014029	ZCGB322BBHV020019	ZCGB322BBHV020075	ZCGB322BBJV020135
ZCGPFGNU5HV014030	ZCGB322BBHV020020	ZCGB322BBHV020076	ZCGB322BBJV020136
ZCGPFGNU7HV014031	ZCGB322BBHV020021	ZCGB322BBHV020077	ZCGB322BBJV020137
ZCGPFGNU9HV014032	ZCGB322BBHV020022	ZCGB322BBHV020078	ZCGB322BBJV020138
ZCGPFGNU0HV014033	ZCGB322BBHV020023	ZCGB322BBHV020079	ZCGB322BBJV020139
ZCGPFGNU2HV014034	ZCGB322BBHV020024	ZCGB322BBHV020080	ZCGB322BBJV020140
ZCGPFGNU4HV014035	ZCGB322BBHV020025	ZCGB322BBHV020087	ZCGB322BBJV020141
ZCGPFGNU6HV014036	ZCGB322BBHV020026	ZCGB322BBHV020088	ZCGB322BBJV020142
ZCGPFGNU8HV014037	ZCGB322BBHV020027	ZCGB322BBHV020089	ZCGB322BBJV020143
ZCGPFGNUXHV014038	ZCGB322BBHV020028	ZCGB322BBHV020090	ZCGB322BBJV020144
ZCGPFGNU1HV014039	ZCGB322BBHV020029	ZCGB322BBHV020091	ZCGB322BBJV020145
ZCGPFGNU8HV014040	ZCGB322BBHV020030	ZCGB322BBHV020092	ZCGB322BBJV020146
ZCGPFGNUXHV014041	ZCGB322BBHV020031	ZCGB322BBHV020093	ZCGB322BBJV020147
ZCGPFGNU1HV014042	ZCGB322BBHV020032	ZCGB322BBJV020094	ZCGB322BBJV020150
ZCGB322BBHV014043	ZCGB322BBHV020033	ZCGB322BBJV020095	ZCGB322BBJV020151
ZCGB322BBHV014044	ZCGB322BBHV020034	ZCGB322BBJV020096	ZCGB322BBJV020152
ZCGB322BBHV014045	ZCGB322BBHV020035	ZCGB322BBJV020097	ZCGB322BBJV020153
ZCGB322BBHV014047	ZCGB322BBHV020036	ZCGB322BBJV020098	ZCGB322BBJV020172
ZCGB322BBHV014048	ZCGB322BBHV020037	ZCGB322BBJV020099	ZCGB322BBJV020184
ZCGB322BBHV014049	ZCGB322BBHV020038	ZCGB322BBJV020100	ZCGB322BBJV020189
ZCGB322BBHV014050	ZCGB322BBHV020039	ZCGB322BBJV020101	ZCGB322BBJV020197
ZCGB322BBHV014051	ZCGB322BBHV020040	ZCGB322BBJV020102	ZCGB322BBJV020199
ZCGB322BBHV014052	ZCGB322BBHV020041	ZCGB322BBJV020103	



NHTSA Campaign Number: 17V772

Date: December 2017

Dear Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

MV Agusta Motor S.p.A has decided that a safety defect exists on a production batch of some rear wheel rims used for our model MV Agusta Brutale 800 Dragster RR produced from 26 June 2017 to 25 September 2017. We are therefore conducting a voluntary safety recall.

YOUR VEHICLE IS AFFECTED

Affected motorcycles have spokes on the rear wheel rim that may be loose or that may become loose, subjecting the rim to potential failure during normal use of the motorcycle, thereby increasing the risk of a crash.

WARNINGS which can precede failure:

If the spokes are loose or become loose, the wheel may react abnormally causing the motorcycle to wobble when ridden. Do not ride your motorcycle under any circumstance.

MV Agusta is taking the following measures to remedy the defect:

- Notifying affected MV Agusta owners.
- Conducting a voluntary recall so that affected vehicles will be inspected and repaired by a MV Agusta dealer, free of charge.
- The recall will involve installing a new rear wheel rim, free of charge.
- The earliest date that a MV Agusta dealer can remedy the defect is 15 December 2017. We ask that you make arrangements with your MV Agusta dealer immediately. The service will take approximately 60 minutes.

IT IS IMPERATIVE TO COMPLETE THE RECALL AS SOON AS POSSIBLE.

Please note that you may submit a complaint to the National Highway Traffic Safety Administration, 1200 New Jersey Ave SE. Washington, DC 20590, or you may call the toll free Auto Safety Hotline at 1-888- 327-4236 (TTY 800 424 9153) or go to www.safercar.gov , if you believe that:

- MV Agusta or your designated repair facility has failed to or is unable to remedy the defect without charge.
- MV Agusta or your designated repair facility has failed to or is unable to remedy the defect without charge within a reasonable time, which is not longer than 60 days after you tender the vehicle to the designated repair facility.

Any Lessor that receives this notification must send a copy of this notice to the Lessee.

Any Dealer that receives this notification must send a copy of this notice to the Customer.

MV Agusta will reimburse an owner who has already incurred costs to obtain a remedy for the problem addressed by this recall (other than caused by accident or abuse) done on affected vehicles prior to the recall.

We apologize for this inconvenience, however we have taken this action in the interest of your safety and continued satisfaction with our products. If you have any questions, please contact:

MV Agusta USA, LLC

10 Canal Street

Suite 224

Bristol, PA 19007

Phone: 215-781-1770

Fax: 215-781-1773



MV AGUSTA MOTOR S.P.A. - SOGGETTA A DIREZIONE E COORDINAMENTO DA PARTE DI MV AGUSTA MOTOR HOLDING S.R.L.
SEDE LEGALE ED AMMINISTRATIVA: VIA G. MACCHI, 144 - SCHIRANNA - 21100 VARESE - ITALY - TEL. +39 0332 254111 - FAX +39 0332 329378
COD. FISC. - P. IVA 02324190129 - REA N° 247420 - CAP. SOC. EURO 26.826.667,00 INTERAMENTE VERSATO - WWW.MVAGUSTA.COM



If you have sold your vehicle or have taken it out of service, please complete the enclosed reply sheet and return it to **MV Agusta USA, LLC** or use the following email address info@mvagusta.com

Your cooperation is appreciated.

Sincerely yours,

MV Agusta Customer Service

.....

To MV Agusta Customer Service

Motorcycle VIN:

Motorcycle cannot be checked because it has been

scrapped

stolen

sold to a domestic buyer

sold to an overseas buyer

to new address:

Name: _____

First name: _____

Street: _____

Zip code: _____ **Town:** _____

Country: _____

Date / signature: