

# Technical Journal

TITLE:

**(MY22) VCM: U210909 Back-up Battery - Updated Instruction**

<b>REF NO:</b> TJ 36425.1.2	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7510 Volvo Car USA		<b>ISSUE DATE:</b> 2022-11-14	<b>STATUS DATE:</b> 2023-01-10
<b>FUNC GROUP:</b> 3970	<b>FUNC DESC:</b> Mobile data services	Page 1 of 2	

**“Right first time in Time”**

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

**DESCRIPTION:**

\*In instances where MY22 vehicles experience VCM “DTC-U210909 Back-up Battery”, and DTC is confirmed, the VCM back-up battery (31450445) should be replaced. Please follow further instruction under Service.

\***Please note:** Do not replace complete VCM unit as previously directed.

**CSC** Customer Symptom Codes

Code	Description
JG	Volvo On Call/Other Volvo On Call problems
KY	Volvo On Call/Does not work

**DTC** Diagnostic Trouble Codes

Control Module	Code	Fault Type
VCM	U210909	Permanent

# Technical Journal 36425.1.2

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2022-2022		-	0-0
225							2022-2022		-	0-0
227							2022-2022		-	0-0
256							2022-2022		-	0-0
536							2022-2022		-	0-0

### SERVICE:

Check to see if MY22 SPA/CMA vehicle(s) has DTC-U210909 set. If so, follow the instruction below:

\*Until this TJ is updated with any further information, please replace the VCM back-up battery (31450445) in the problem vehicle.

### Warranty claim info:

This TJ is for informational purposes only, therefore there is not an associated labor operation.

### VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3970.