



Parts Bulletin

TITLE:

**Service Action S29878: Fuel Tank Filler Pipe
Model Year 2017 - 2018 XC90, S90, V90, V90CC, XC60**

GROUP: 23	CAT/NO: S29878	REFERENCE BULLETINS: Quality Bulletin S29878	CAR MARKET: United States and Canada		
COPY TO / CIRCULATIONS (PLEASE INITIAL):				DATE:	
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	YEAR 2018	MONTH 09
				DAY 06	
					Page 1 of 1

“Right first time in Time”

Reference Bulletins: Quality Bulletin S29878

Volvo Car USA LLC and Volvo Car Canada LTD (Volvo) on behalf of Volvo Car Corporation, has decided to launch Service Action S29878 on certain model year 2017 - 2018 XC90, S90, V90, V90CC, XC60 vehicles.

Volvo has identified that the lower flap in the capless unit that is located inside the fuel tank filler pipe, intermittently may not close completely after refueling. This could result in a Check Engine Light and Diagnostic Trouble Code ECM-P0044200.

The corrective action is to replace the fuel tank filler pipe per VIDA instruction VCC-501692-1.

Service Campaign S29878 affects 14,911 vehicles in the U.S. and 1,183 in Canada.

The following part numbers apply:

Part Number	Description	Qty
32242544 XC60	Fuel Filler Pipe	1
32242545 XC90	Fuel Filler Pipe	1
32242547 S90, V90, V90CC	Fuel Filler Pipe	1