



# Technical Journal

TITLE:

**Left engine pad click sound**

<b>REF NO:</b> TJ 33442.6.0	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7510 Volvo Car USA		<b>ISSUE DATE:</b> 2018-10-16	<b>STATUS DATE:</b> 2018-10-22
<b>FUNC GROUP:</b> 2180	<b>FUNC DESC:</b> Engine mounting	Page 1 of 2	

“Right first time in Time”

## Attachment

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-2099		-	201617-209952
235							2017-2099		-	201624-209952
236							2017-2099		-	201646-209952
238							2017-2099		-	201646-209952
246							2018-2099		-	201717-209952
256							2016-2099		-	201505-209952

## CSC Customer Symptom Codes

Code	Description
F3	Complete vehicle/Unusual noise/During acceleration
F2	Driving/Unusual noise/During acceleration

## VST Operation Number

VST Operation Number	Description
21815	Engine pad left replace



## **DTC** Diagnostic Trouble Codes

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

## **Text**

### **DESCRIPTION:**

\*Vehicles added.

If the vehicle has a click sound from the left engine pad, (a metallic click sound from A-pillar area)  
Follow the advice under "Service".

### **SERVICE:**

\* Replace engine pad.

New service solution is under validation.

### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if click sound returns after repair. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 2180.