



Technical Journal

TITLE:

Trunk lid difficult to open

REF NO: TJ 33432.2.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2018-01-22	STATUS DATE: 2018-02-05
FUNC GROUP: 8320	FUNC DESC: Boot lid, tailgate with hinge and suppor	Page 1 of 3	

“Right first time in Time”

Attachment

File Name	File Size
TJ33432.JPG	0.0688 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-9999		0000350-9999999	201617-999952
238							2018-9999		0000161-9999999	201646-999952

CSC Customer Symptom Codes

Code	Description
1K	Tailgate/trunk lid/Automatic opening/closing does not work
WJ	Tailgate/trunk lid/Hard to open

VST Operation Number

VST Operation Number	Description
99400-2	General reimbursement acc. to TJ/QB

DTC Diagnostic Trouble Codes

Text

**DESCRIPTION:**

If the trunk lid is difficult to open, it may be due to the incorrect spring position. Follow advice under service.

SERVICE:

Check the trunk lid spring, see attachment.


Position A is vehicle with accessory spoiler on trunk lid.

Position B is vehicle without accessory spoiler on trunk lid.


VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8320.

To view TJ attachment continue to next page. This TJ has one attachment.



A



B

TJ33432