



Technical Journal

TITLE:

Roller blind, rattle noise when opening

REF NO: TJ 33183.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2018-02-09	STATUS DATE: 2018-02-14
FUNC GROUP: 8364	FUNC DESC: Sun visor, roof hatch	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
235							2017-2018		-	201624-201728
236							2018-2018		-	201646-201728
246							2018-2018		-	201717-201728
256							2016-2018		-	201505-201728

CSC Customer Symptom Codes

Code	Description
B2	Sun/moon/convertible roof/Squeak/rattle

VST Operation Number

DTC Diagnostic Trouble Codes

Text

DESCRIPTION:

If a vehicle with panorama roof shows symptom of a rattling noise when opening, follow the description under Service.

**SERVICE:**

If the analysis shows that the rattling noise comes from the roller blind, similar to the noise in the attached file, replace the roller blind according to VIDA.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8364.

This TJ has a [sound file](#).