

Jason Guidi

Director - Regulatory & Compliance

July 16, 2018

To: All U.S. and Canadian Volvo Retailers Subject: Service Campaign A39894: Park Assist System **May Not Function as Intended**

Volvo Car USA LLC and Volvo Car Canada Ltd on behalf of Volvo Car Corporation, has decided to launch Service Campaign A39894 on certain model year 2019 XC90, XC60, V90CC, V90 and S90 vehicles.

Volvo has identified that the vehicles equipped with a front and/or rear park assist system (PAS) may not function as intended. However the rear park assist camera functions as intended.

The corrective action is to perform a Total Upgrade.

PLEASE NOTE: PDS software must be installed in the vehicle within 5 days of delivery. Vehicles that have had a Total Upgrade at PDS completed prior to 7/2/18 must have the Total Upgrade performed again, and a claim submitted per the instructions in this action. Vehicles with a Total Upgrade performed at PDS after 7/2/18 have already received the Park Assist software and do not require any further action, and a claim should not be submitted.

Service Campaign A39894 affects 6,628 vehicles in the U.S. and 676 in Canada.

Service Campaign A39894 will be in effect until <u>December 31, 2020</u> regardless of mileage.

OWNER NOTIFICATION

A customer mailing to vehicle owners that have taken delivery prior to 7/2/18 is scheduled for late August.

Volvo Car USA LLC 1 Volvo Drive Rockleigh, NJ 07647



RETAILER RESPONSIBILITIES

Retailers must perform this service campaign on eligible vehicles regardless of miles / kilometers or vehicle age. All work performed under this service campaign is free of charge to the owner.

Your regional representative will follow up to ensure that Service Campaign A39894 is proceeding smoothly.

A complete description of the service campaign requirements and claim submission procedures will follow.

It is the retailer's responsibility to review the details provided in the materials listed below with all involved personnel.

- Quality Bulletin
- Parts Bulletin

Your cooperation in completing Service Campaign A39894 is greatly appreciated.

All vehicles should be checked for any other incomplete actions.

If you have any questions about this or any other field service action, please contact me or any member of the Regulations and Compliance office.

Drive Safely,

Jam J Suidi

Jason Guidi Director - Regulatory & Compliance 201-768-7300 jason.guidi@volvocars.com VOLVO CAR SERVICE AND PARTS BUSINESS



Quality Bulletin

TITLE:

Service Campaign A39894: Park Assist System May Not Function as Intended Model Year 2019 – XC90, XC60, V90CC, V90, S90

GROUP:	CAT/NO:	ISSUING DEPARTMENT:		CAR MARKET:		
30	A39894	Warranty		United States and Canada		
REFERENCE BULLETINS:				ISSUE DATE:	STATUS DATE:	
PB 30-A39894				2018-07-17	2018-09-25	
Service Personnel:		SERVICE	SERVICE	WARRANTY	Page 1 of 3	
Read and initial		MANAGER	WRITER	ADMINISTRATOR		

"Right first time in Time"

Bulletin Updates: Sections "A" and "F" are updated.

BULLETIN REFERENCE PB 30-A39894

- A. SERVICE CAMPAIGN A39894 DESCRIPTION
- **B. VEHICLES INVOLVED**
- C. PARTS INFORMATION/PARTS RETURN
- **D. OWNER NOTIFICATION**
- E. VEHICLES IN RETAILER INVENTORY
- F. RETAILER RESPONSIBILITY
- G. TECHNICIAN COMPETENCY REQUIREMENT
- H. CLAIM INSTRUCTIONS

A. SERVICE CAMPAIGN A39894 DESCRIPTION

Volvo Car USA LLC and Volvo Car of Canada Ltd on behalf of Volvo Car Corporation, has decided to launch Service Campaign A39894 on certain model year 2019 XC90, XC60, V90CC, V90 and S90 vehicles.

Volvo has identified that the vehicles equipped with a front and/or rear park assist system may not function as intended. However the rear park assist camera functions as intended.

The corrective action is to perform a Total Upgrade.

Vehicles in stock are not eligible for submission under this campaign. Software will be updated as part of the required PDS software installation policy within 5 days of retail delivery.

Service Campaign A39894 affects 6,628 vehicles in the U.S. and 676 in Canada.

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste. © 2018 VOLVO CAR USA, LLC



RETAILER MUST CONFIRM VEHICLE ELIGIBILITY PRIOR TO BEGINNING THE REPAIR FOR THIS ACTION.

Vehicles in retailer inventory must have a Total Upgrade performed per the PDS instructions prior to sale.

<u>PLEASE NOTE</u>: Service Campaign A39894 will be in effect until <u>December 31, 2020</u>, regardless of mileage.

B. VEHICLES INVOLVED

NOTE: RETAILER MUST CONFIRM VEHICLE ELIGIBILITY PRIOR TO BEGINNING THE REPAIR FOR THIS SERVICE ACTION.

Vehicle eligibility must be confirmed:

• Inquire in VRC² - Vehicle Warranty where the message "Service Campaign A39894 Park Assist" will appear for eligible vehicles.

All vehicles should be checked for any incomplete recalls, service campaigns or service upgrades. All open Recall, Service Campaign or Service Action repairs should be completed.

C. PARTS INFORMATION / PARTS RETURN

Please refer to Parts Bulletin 30-A39894 for parts information.

PARTS RETURN

No parts are required to be returned to TMA for this service campaign.

D. OWNER NOTIFICATION

A customer mailing to vehicle owners that have taken delivery prior to 7/2/18 is scheduled for late August.

E. VEHICLES IN RETAILER INVENTORY

Please refer to section "F" below.

F. RETAILER RESPONSIBILITY

Vehicles in stock are not eligible for submission under this campaign. Software will be updated as part of the required PDS software installation policy within 5 days of retail delivery.

G. TECHNICIAN COMPETENCY REQUIREMENT

The technician competency requirement for this repair is Level 2 Certified Tech.



H. CAMPAIGN REIMBURSEMENT PROCEDURES (LONG FORM APPLICATION)

Labor reimbursement is effective at time of release and may change in the future.Claim Type:A39894Cause Code:02CSC Code:XWMain OP:97612Failed Part:31472405, 31654144, 31483292

Operation Number	Repair Description	<u>Oty</u>	<u>Labor Time</u>
97612	Total Upgrade per QB A39894	1	0.7 hrs

VOLVO CAR SERVICE AND PARTS BUSINESS



Parts Bulletin

Service Campaign A39894: Park Assist System May Not Function as Intended Model Year 2019 – XC90, XC60, V90CC, V90, S90

TITLE:

GROUP: 30	CAT/NO: A39894	REFERENCE BULLETINS: QB A39894		CAR MARKET: United States and Canada	
COPY TO / CIRCULATIONS (PLEASE INITIAL):				ISSUE DATE:	STATUS DATE:
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	2018-07-17	2018-09-25
				Page 1 of 1	

"Right first time in Time"

Bulletin Updates: Paragraph 4 is updated.

Reference Bulletins: QB A39894

Volvo Car USA LLC and Volvo Car of Canada Ltd on behalf of Volvo Car Corporation, has decided to launch Service Campaign A39894 on certain model year 2019 XC90, XC60, V90CC, V90 and S90 vehicles.

Volvo has identified that the vehicles equipped with a front and/or rear park assist system may not function as intended. However the rear park assist camera functions as intended.

The corrective action is to perform a Total Upgrade.

Vehicles in stock are not eligible for submission under this campaign. Software will be updated as part of the required PDS software installation policy within 5 days of retail delivery.

Service Campaign A39894 affects 6,628 vehicles in the U.S. and 676 in Canada.

Service Campaign A39894 will be in effect until <u>December 31, 2020</u>, regardless of mileage.

The following part numbers apply:

Part Number	Description	Qty
31472405	Total Upgrade S90	1
31654144	Total Upgrade V90, V90CC	1
31483292	Total Upgrade XC90, XC60	1

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste. © 2018 VOLVO CAR USA, LLC