



GROUP
ELE

MODEL
2011MY
Optima Hybrid
(TF HEV)

NUMBER
019

DATE
October 2011

TECHNICAL SERVICE BULLETIN

SUBJECT: SERVICE ACTION: OPTIMA HEV HYBRID COOLING
FAN RESISTOR REPLACEMENT (SA094)

This bulletin provides information about some Optima Hybrid vehicles produced from Job #1 to September 17, 2011 where the cooling fan resistor might crack. If the cooling fan resistor is cracked, the cooling fan operation may be affected. To ensure maximum customer satisfaction Kia is requesting the completion of this Service Action on all affected 2011MY Optima Hybrid vehicles. Before conducting this Service Action, verify that the VINs included in the list of the affected VINs.



* NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA094.

File Under: <Electrical>

Circulate To: General Manager Service Manager Parts Manager
 Service Advisors Technicians Body Shop Manager Fleet Repair