

Reference	SSM74187
Models	F-PACE / X761
Title	X761 F-Pace Roof Opening Panel - Low Lever Service Repair
Category	Body
Last modified	02-Jan-2019 00:00:00
Symptom	105000 Roof Options
Content	<p>Issue:</p> <p>Customers may report one or more of the following issues with the roof opening mechanism.</p> <ul style="list-style-type: none"> • Jammed • When opening in tilt only one side opens. • A rattle from the the guide rail mechanism. <p>Cause:</p> <p>Concerns with the roof opening panel guide rails.</p> <p>Action:</p> <p><u>Do not</u> order a complete panoramic roof frame.</p> <p>Jaguar Engineering have released a low level service repair for any of the above symptoms</p> <p>Refer to Topix, Section 501-17 Roof Opening Panel - Removal and Installation - Roof Opening Panel Guide Rails.</p> <p>Jaguar F-Pace Service Part Numbers:- Left Hand Guide Rail = T4A33021 Right Hand Guide Rail = T4A33020</p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>