


Latest Vehicle Concern Fixes



	XE 17-18MY, XF 16-18MY
<p>Climate Control Drain Tube Leak</p> <p>Customer Voice:</p> <ul style="list-style-type: none">Customers may express a concern of water ingress into the front footwells. <p>Technical Description:</p> <ul style="list-style-type: none">This may be caused by a climate control system drain tube that is not sealing properly. <p>Status:</p> <ul style="list-style-type: none">Revised drain tubes have been created to address this concern.TSB JTB00670NAS1 is going through sign-off to provide repair guidance and new drain tube part numbers.	 A technical diagram showing a blue flexible drain tube connected to a blue plastic housing. An inset image shows a close-up of the tube's end, which has a purple, multi-lobed seal. The diagram is labeled "E21178" in the bottom right corner.

