



SI B63 01 19
Lights

January 2019
Technical Service

DELIVERY STOP: REAR LAMP

New information provided by this revision is preceded by this symbol  .

This Service Information bulletin has been **updated since January 22, 2019**.

What's New:

- Models have been removed – F22 F23 (2 Series), F87 (M2 Competition)
- F48 (X1) vehicles have been transferred to SIB B63 02 19 (0063570100)
- Situation has been updated

MODEL

 F39 (X2 SAV)

 **SITUATION**

This Delivery Stop was issued (effective January 22, 2019) and involves the rear lamp assembly's mounting bracket.

Approximately 2,084 vehicles are now affected by this delivery stop.

Do not deliver to a customer, a New, Certified Pre-Owned or Used vehicle subject to a Delivery Stop, until the vehicle is repaired. Do not use or sell replacement equipment/parts subject to a Delivery Stop.

Affected vehicles show the campaign as "Open" when checked either in Warranty Vehicle Inquiry, AIR or ISPA Next and identified with the description: STOP213627 B630119 Delivery Stop: Rear Lamp.

The bulletin will be updated when more information becomes available.

Posted: Thursday, January 31, 2019

[Copyright ©2019 BMW of North America, Inc.]