

WORK DESCRIPTION FOR FIELD MEASURE

Code: 1805P54B33

Version: 2.0

Update Audio 20 or COMAND Online control unit software

Models 205 and 238

- i** • Ensure use of **XENTRY Diagnosis version** BD/DVD (**09/2018**) or higher.
 - Before starting any work procedure, install all the **updated add-ons** in **XENTRY Diagnosis**.
 - Please make sure to follow the operation steps exactly as described in XENTRY Diagnosis.
 - Use a battery charger to ensure sufficient power supply of the vehicle **on-board electrical system battery** (greater than 12.5 V).
 - If XENTRY Diagnosis is already connected to the vehicle, start with **operation step 2**.
- i** If two or more software updates or SCN codings are performed during one workshop visit, operation items 02-4762 and 02-5058 must be invoiced **only once for each workshop order!**

Work procedure

1. Connect XENTRY Diagnosis.
2. Update Audio 20 or COMAND Online control unit software.
 - i** To do this, select menu item “Quick test view – A26/17 Audio 20 (Audio) or A26/17 COMAND Online – Adaptations – Control unit update – Update control unit software“.
 - i** Then follow the user guidance in XENTRY Diagnosis.
3. Delete fault memory after software update.
 - i** System-related faults are stored in the fault memory during software updates.
4. Disconnect XENTRY Diagnosis.

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-2702*	Update Audio/COMAND control unit software (XENTRY Diagnosis connected) Acc. no.: 54 997 43 ; code: 1805P54B33	0.3 h	54 997 43
02-4762**	Connect/disconnect vehicle diagnosis system (XENTRY Diagnosis)	0.1 h	54 997 43
02-5058**	Connect/disconnect starter battery charger (XENTRY Diagnosis connected)	0.1 h	54 997 43

* Enter the code and accounting number manually in the workshop order as per the work instructions.

** Operation item may be invoiced only once for each workshop order!

Mercedes-Benz
Global Service & Parts