



Countries: CANADA, UNITED STATES **Document ID:** IK1100034
Availability: ISIS, FleetISIS, IsSIR **Revision:** 3
Major System: CLUTCH **Created:** 12/14/2018
Current Language: English **Last Modified:** 1/17/2019
Other Languages: NONE **Author:** David Horner
Viewed: 156

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 3	Not Helpful 0
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------

Title: Heavy Duty Clutch May Not Acheive Full Departure

Applies To: Heavy Duty Solo Clutch

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

12/14/2018 - Internal Article Release

DESCRIPTION

Please refer to Eaton Service Bulletin, "[CLIB-0035 Heavy Duty Clutch May Not Achieve Full Departure – Mechanical and Automated](#)", for additional information.

Hide Details

Feedback Information

Viewed: 155
 Helpful: 3
 Not Helpful: 0

No Feedback Found