



# Preliminary Information

## PIP5337K Shake Or Shudder On Acceleration

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
Cadillac	Escalade ESV	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
Chevrolet	Corvette	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
Chevrolet	Silverado	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
GMC	Sierra	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
GMC	Yukon	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U
GMC	Yukon XL	2015 - 2016	SOP	Built prior to 11/01/15	6.2L RPOs L86 and LT1	8L90 Automatic Transmission RPOs M5U

Please refer to bulletin [16-NA-175](#) for vehicles equipped with the 8L90 automatic transmission RPO (M5U) with shudder concerns.

Please follow this diagnostic or repair process in Bulletin [16-NA-175](#), thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed."



GENERAL MOTORS