



Technical Tip

Topic	55-19-01TT - Power Rear Lid Operation
Market area	United States 444 Volkswagen of America, Inc. (444)
Brand	Volkswagen
Date	January 18, 2019

Condition

ATTENTION:**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.****TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Power Rear Lid Operation

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas, Tiguan LWB	2018-2019	All	All	All	All

Technical Background

Rear lid only opens approximately $\frac{1}{4}$ of the way, when using power rear lid function.

Rear lid latch not allowing the rear lid to open fully.

Service

If the rear lid will not open more than about one quarter to one third of the way, check circuit integrity/wiring to the latch. If there are no concerns noted, replace the latch and retest operation.

Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2053641/1	1/18/19	Original publication.

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.