CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD

RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They

are written to inform those technicians of conditions that may occur in some vehicles, or

to provide information that could assist in the proper servicing of the vehicle. Properly

IMPORTANT - All

INTRODUCTION

The purpose of this bulletin is to clarify the proper installation direction of the valve springs used on the FA engine. The springs have a light blue paint mark identifier as shown in the chart below.

Important Installation Notes:

- When installing the new type valve spring, the end with the paint mark must always face upward and be against the valve spring retainer.
- Whenever a failed valve spring is identified, all sixteen(16) springs must be replaced AS A SET.

PART INFORMATION	
------------------	--

	NEW TYPE	OLD TYPE
Part Name	SPRING-VALVE ENGINE	
Part Number	13217AA521 13217AA520	
Identification	Light Blue Paint Mark	Green Paint Mark
Installation Direction	The Light Blue paint mark must install against the spring retainer.	NO

Continued...

SUBARU OF AMERICA, INC. IS "ISO 14001 COMPLIANT" The international standard for excellence in Environmental Management Systems.

in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.



QUALITY DRIVEN® SERVICE

02-133-12R

08/16/12

01/31/19

NUMBER:

REVISED:

DATE:

SERVICE BULLETIN

APPLICABILITY:	2012-10 MV BB7
	2013 <mark>-19</mark> IVI I BRZ

ATTENTION:

SUBJECT: Valve Spring Information

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.