


SERVICE MANUAL BULLETIN

This Service Manual Bulletin is prepared by the Publications Department of New Flyer Industries Canada ULC. Refer to details below.

SMB-183

ISSUE DATE: Jan 25 2019

APPLICABILITY					
VEHICLE LENGTH	<input type="checkbox"/> 30ft.	<input type="checkbox"/> 35ft.	<input type="checkbox"/> 40ft.	<input type="checkbox"/> 60ft.	<input checked="" type="checkbox"/> ALL
VEHICLE TYPE	<input checked="" type="checkbox"/> Xcelsior®	<input type="checkbox"/> MiDi®	<input type="checkbox"/> Invero®		<input type="checkbox"/> ALL
	<input type="checkbox"/> Low Floor	<input type="checkbox"/> High Floor			
FUEL TYPE	<input type="checkbox"/> Diesel	<input type="checkbox"/> Diesel/Electric	<input type="checkbox"/> CNG	<input type="checkbox"/> LNG	<input type="checkbox"/> ALL
	<input type="checkbox"/> Fuel Cell	<input type="checkbox"/> Trolley/Electric	<input checked="" type="checkbox"/> Battery/Electric		
SUBJECT	Roof Vent/Hatches				
SECTION TITLE	This information applies to your Operator's Guide and Service Manual				
DETAILS	<p>This bulletin adds a WARNING regarding safety when charging the vehicle.</p> <div style="text-align: center;">  <p>WARNING</p> </div> <p>DO NOT open the roof hatch when the high voltage batteries are being charged.</p> <p>This bulletin supersedes any prior information on this subject already provided in your New Flyer Service Manuals. Make this Service Bulletin available to service personnel to inform them of changed information.</p>				