



Service Bulletin

Bulletin No.: 18-NA-224

Date: February, 2019

TECHNICAL

Subject: Head-Up Display (HUD) Inoperative, Malfunction Indicator Lamp (MIL) Illuminated - DTC U1518 Set

This Bulletin replaces PIC6310A. Please discard PIC6310A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	LaCrosse	2017	2018				
Cadillac	XT5						
Chevrolet	Camaro	2016	2019				

Involved Region or Country	North America and N.A. Export Regions
Additional Options (RPOs)	Equipped with Head-Up Display (RPO UV6)
Condition	<p>Some customers may comment on one or more of the following conditions:</p> <ul style="list-style-type: none">• MIL is illuminated• HUD is inoperative <p>Some technicians may find DTC U1518 (P16 Instrument Cluster Lost Communication with K78 Head-Up Display Module / P29 Head-Up Display on LIN Bus) set in the Control Module.</p> <p>Some technicians may also experience No HUD Communication with GDS2.</p>
Cause	This condition may be caused by an internal HUD software concern.
Correction	If this concern is experienced, replace the HUD.

Service Procedure

Refer to *Head-Up Display Replacement* in SI.

Parts Information

Causal Part	Description	Part Number	Qty
X	DISPLAY, HEAD UP	Refer to the Electronic Parts Catalog (EPC) with VIN	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
3431810	Head-Up Display Replacement	Use Published Labor Operation Time

Version	2
Modified	Released July 12, 2018 February 08, 2019 – Added the 2016-2019 Camaro models.

