



Service Bulletin

Bulletin No.: PIE0488A

Date: February, 2019

ENGINEERING INFORMATION

Subject: Engineering Information – Harness Rubbing on Battery Tray

This PI has been revised to end the need for information from the field.
Please discard PIE0488.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2017	2018			Equipped with 1.5L Engine (RPO LfV)	Equipped with 6 Speed Automatic Transmission (RPO MNH)

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released September 20, 2018 February 15, 2019 – Ended the need for further information from the field.