



GROUP  
**Climate**

MODEL  
**2016MY  
Sorento (UMa)**

NUMBER  
**027**

DATE  
**February 2015**

## TECHNICAL SERVICE BULLETIN

**SUBJECT: SERVICE ACTION: A/C SUCTION HOSE/PIPE INSPECTION  
AND/OR MODIFICATION (SA 183)**

This bulletin provides the procedure to inspect and, if necessary, correct the routing for the A/C suction hose/pipe on some 2016MY Sorento (UMa) vehicles, produced from October 27, 2014 through February 9, 2015, to prevent possible contact between the suction hose/pipe and the compressor pulley. To correct and/or prevent this contact, follow the procedure outlined in this bulletin. Kia is requesting the completion of the Service Action on all affected vehicles, including dealer stock, prior to delivery. Before performing the procedure, verify the vehicle is included in the list of affected VINs.



### ★ NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service> Warranty Coverage> Warranty Coverage Inquiry> Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs> Not Completed Recall> Recall VIN> Select Report), which includes a list of affected vehicles.

This issue number is SA183

File Under: <Climate >

Circulate To: ☒ General Manager ☒ Service Manager ☒ Parts Manager

☒ Service Advisor(s) ☒ Technician(s) ☒ Body Shop Manager ☒ Fleet Repair