

Measure no.

US 64678027-01

Subject

Seat is difficult to close

Status date (mm/dd/yy)

1/18/19

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

1/18/19

Created by

Michael Gersbach

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K09

Engine**Body****Production period (from/to)**

(mm/dd/yy)

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

/

Complaint

Seat catch (striker) fits improperly in the seat lock.

Cause

The tolerance between the catch and seat lock is too tight

Measure

Currently changing the seat or seat lock does not provide a solution.

The seat will be optimized so that the catch fits appropriately into the seat lock.

The optimized seat is expected to be available for ordering by the end of June.

Complaint**Fault location**

51/25 Seat lock

Fault typeCannot be encoded with
VFC**Fault place**

Cause

#

Fault location**Fault type****Fault place**

1

51/25 Seat lock

Repair Task	Special Clearance	Area
	No	Body and Trim
Fault code		
Progman / DIS / ISTA / ISTA/P		
System	State	Version

© 2002-2019 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.