



Service Bulletin

Bulletin No.: 18-NA-222

Date: January, 2019

TECHNICAL

Subject: Creak Type Noise Heard from Front End While Driving Over Bumps

Brand:	Model:	Model Year:		Breakpoint		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2018	2018				
GMC	Terrain						

Involved Region or Country	Mexico and South America.
Condition	Some customers may comment on a creak type noise heard from the front end while driving over bumps.
Cause	This condition may be caused by the current front lower control arm bushings.
Correction	Replace the front lower control arm bushings with the revised part.

Service Procedure

Refer to Front Lower Control Arm Rear Bushing Replacement in SI.

Parts Information

Causal Part	Description	Part Number	Qty
X	BUSHING, FRT LWR CONT ARM RR	84662074	2

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8033370	Front Lower Control Arm Rear Bushing Replacement	Use Published Labor Operation Time

Version	1
Modified	Released January 18, 2019

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION