



# Service Bulletin


Bulletin No.: 17-NA-302

Date: January, 2019

## INFORMATION

**Subject:** Dust, Snow or Water Around Fuel Filler Area

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado	2017	2018				
	Silverado LD	2019	2019				
	Silverado 2500/3500						
GMC	Sierra	2017	2018				
	Sierra Limited	2019	2019				
	Sierra 2500/3500						

<b>Involved Region or Country</b>	North America and NA Export vehicles
<b>Condition</b>	Some customers may comment on excess amount dirt, snow or water that can build up around the fuel filler neck.
<b>Cause</b>	This condition may be caused when trucks are operated in high amount of dirt, dust or snow which can migrate to the filler cap area.
<b>Correction</b>	 <p>4869504</p> <p>Notify the customer that GM has made available a locking gas cap for drivers that operate in these environments. This will help to protect the fill area and the fuel system.</p>

**Parts Information**

Causal Part	Description	Part Number	Qty
x	CAP ASM-F/TNK FIL LKG	84009129 (2017)	1
		84308352 (2018–2019)	

<b>Version</b>	3
<b>Modified</b>	Released January 11, 2018 Revised February 15, 2018 – Updated information under the Subject, Condition, Cause and Correction. Revised January 15, 2019 – Added 2019 Silverado LD, Silverado 2500/3500, Sierra Limited, Sierra 2500/3500 and updated the Parts Information.

