

A welcome image is not shown on the instrument cluster.

Topic number	LI54.30-P-069433
Version	1
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	02-19-2019
Validity	Model series 205/213/217/222/238/253 with code 809 and code B01 (48 V technology) Model series 205/213/217/222/238/253 with code 808 and code 058 (Modification year 17/2) and code B01 (48 V technology)
Reason for change	
Reason for block	

Complaint:

The instrument cluster does not show a welcome image.

Cause:

In vehicles with 48 V on-board electrical system, the animation is disabled.

Remedy:

This is by design and there will be no further changes that will be made to incorporate the welcome message.

Symptoms
Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Menu items missing
Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Incomplete display
Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Faulty display

Control unit/fault code		
Control unit	Fault code	Fault text
A1 - Instrument cluster (IC) (IC213) (E (213),S (217),S (222),C (205),E (238))	-	-