

## Ambient lighting remains white

---

Topic number	LI82.20-P-069458
Version	1
Function group	82.20 Interior lights
Date	02-21-2019
Validity	Model series 177 vehicles with ambient lighting (code 877)
Reason for change	
Reason for block	

---

### Complaint:

Ambient lighting remains white and cannot be adjusted even after switching terminal.

### Cause:

Software error in the ambient lighting control unit.

### Remedy:

Update software for ambient lighting control unit (N162) when this occurs.

<b>Symptoms</b>
Lighting / Interior illumination / Ambiance illumination / Does not go on