

Technical Journal

TITLE:

Rear tow hook cover, comes loose

REF NO: TJ 33542.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada		
3 US 7	PARTNER: '510 Volvo Car USA	ISSUE DATE: 2019-01-15	STATUS DATE: 2019-01-21	
FUNC GROUP: 8619	FUNC DESC: Miscellaneous	Page	1 of 3	

"Right first time in Time"

Attachment

File Name	File Size
Reference.png	0.3883 MB
TJ33542.jpg	0.0657 MB

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
238							2018-9999		0000001-9999999	201646-999952
246							2018-2019	36	0024576-0238231	201746-201833

CSC Customer Symptom Codes

Code	Description
M3	Exterior trim/components/Moldings, trim loose
M5	Exterior trim/components/Other trim problems

VST Operation Number

VST Operation Number	Description
99921-2	General reimbursement acc. to TJ/QB

DTC Diagnostic Trouble Codes

Technical Journal 33542.1.0



Text

DESCRIPTION:

If the rear tow hook cover comes loose, follow the advice under service.

SERVICE:

Use tape P/N 30643492 (50x25x0.6) and cut a small piece 8x11 mm.

Apply the tape on the locking tab in order to increase the thickness of the tab on the loose cover or the new cover, see attachment TJ33542.jpg.

VEHICLE REPORT:


Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8619.


To view TJ attachment continue to next page. This TJ has two attachments.

Page 2 of 3 2019-01-21



Technical Journal 33542.1.0





2019-01-21 Page 3 of 3