



Technical Journal

TITLE:

Hard to fill fuel due to frozen filler pipe

REF NO: TJ 34215.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2019-01-14	STATUS DATE: 2019-01-21
FUNC GROUP: 2340	FUNC DESC: Fuel tank, fuel lines, evaporator system	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-2018	21	0000350-0039206	201617-201745
235							2017-2019	21	0000160-0095082	201624-201840
236							2017-2019	21	0000098-0075791	201646-201840
256							2016-2019	21	0000001-0453709	201505-201840

CSC Customer Symptom Codes

Code	Description
BT	Fuel system/Slow fuel tank fill or spitback
8H	Fuel-filler door/Hard/impossible to open
8I	Fuel-filler door/Hard/impossible to close

VST Operation Number

VST Operation Number	Description
98721-2	Lock unit fuel tank filler cover replace acc. to TJ34215

DTC Diagnostic Trouble Codes



Text

DESCRIPTION:

In cases when customer complains regarding difficulties to refuel due to frozen filler pipe, please follow advise under “service”.

SERVICE:

Replace the fuel door latch according to VIDA. New fuel door latches were released 2018w40 with new sealing concept.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support not needed”, use function group 2340.