



Technical Journal

TITLE:

Tail light assembly, replacement or adjustment

REF NO: TJ 34506.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2019-02-15	STATUS DATE: 2019-02-19
FUNC GROUP: 3531	FUNC DESC: Stop lamp; tail lamp; direction lamp	Page 1 of 3	

“Right first time in Time”

Attachment

File Name	File Size
TJ34506.jpg	0.0370 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
235							2017-9999		0000001-9999999	201624-999952
236							2017-9999		0000001-9999999	201646-999952

CSC Customer Symptom Codes

Code	Description
9H	Tail light/Moisture/mist on inside of lens
JL	Side marking lights or position lights/Does not work
FR	Tail light/Does not work

VST Operation Number

VST Operation Number	Description
35317	Tail light assembly 2 pcs. Replace
35310	Tail light assembly 1 pc. Replace



DTC Diagnostic Trouble Codes

Text

DESCRIPTION:

When replacing or adjusting the tail light assembly, the upper screw (see attachment) needs to be secured with thread-locker, follow advise under service.

SERVICE:

Apply thread locker P/N: Wurth 0893243050 on the screw threads P/N: 30624359.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3531.

To view TJ attachment continue to next page. This TJ has one attachment.

