


Latest Vehicle Concern Fixes



Oil Dilution Concerns	16MY RR & RR Sport 3.0L TDV6
<p>Customer Voice:</p> <ul style="list-style-type: none">• Service Required message appears sooner than expected <p>Technical Description:</p> <ul style="list-style-type: none">• Oil Dilution reaches a level seemingly prematurely causing the service required message to appear. <p>Status:</p> <ul style="list-style-type: none">• Ensure the customer drive cycle is documented and they are educated on regen if their drive cycle is less than ideal. Leak check intake & exhaust system, ideally with UV dye. Address any leaks that arise. Raise a TA, and follow the advice of LTS.	 <p>The image shows a close-up of a vehicle's instrument cluster. A central digital display shows the time '2:30 pm' and the date '29'. Below the time, a wrench icon is displayed with the text 'Service Required In 1500miles'. A callout box above the wrench icon also contains the text 'Service Required In 1500miles'. The instrument cluster includes a tachometer on the left, a speedometer on the right, and a gear indicator in the center. The speedometer shows a current speed of 86 mph and a maximum speed of 150 mph. The tachometer shows a current RPM of 2750 and a maximum RPM of 6000.</p>

