

Latest Vehicle Concern Fixes



GTDi Camshaft Bearing Wear

14-17 MY Discovery Sport and Evoque

Customer Voice:

- The vehicle will not start.
- The Check Engine Light is on, there is noise from the engine.

Technical Description:

- Wear is noted on the camshaft bearing surfaces.

Status:

- There has been an increase in reports of this damage over the past weeks.
- We are working to better understand all contributing factors to this damage.
- Ensure proper maintenance has been carried out on any vehicle exhibiting this condition. Inspect the oil and oil filter for contamination to assist in determining correct level repair.
- Raise a TA case which includes pictures of the damage and an oil sample along with maintenance records for the vehicles to determine correct level repair.

