

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
 Freightliner Dealers – U.S. and Canada
 Western Star and Sterling Dealers – U.S. and Canada
 FCCC Dealers – U.S. and Canada
 Direct Warranty Customers – U.S. and Canada
 Export Distributors

Daimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090

800-547-0712

Portland, Oregon 97208-4090

If you have questions about this Letter, please submit your inquiry on the Web using the [WSC Link on DTNAConnect](#)

REF #: ICI19-019

Effective: 01/25/19

Release: 02/18/19

SUBJECT: FL799 - Revised Bulletin

This letter is to inform you that a revised bulletin for **Recall FL799 Honeywell Brake Light Pressure Switches** is available on DTNAConnect. Please print and use the revised bulletin for all work under FL799 from this point forward.

REVISIONS:

- Step 4. Disconnect and remove the brake list pressure switch. **See Fig. 1.** Tag the switch for return per the Warranty Failed Parts Tracking shipping instructions.
- **NOTE:** If the date code on the existing pressure switch falls outside the suspect date code, it still needs to be replaced. The date code inspection is only to prevent installation of dealer stock pressure switched with suspect date codes.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNAConnect.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.