

MFR Communication ID	MFR Communication Date	Make (Brand)	Model	Model Year	Text
SSM 47865	3/15/2019	Lincoln	Continental	2019	Some 2019 Continental vehicles built on or before 11-Feb-2019 may experience a concern where the compass only points North, the clock cannot be set using the "Reset Clock to GPS Time" feature and/or the Navigation will be inoperative. Do not attempt any repairs at this time. Engineering is investigating, monitor OASIS for updates.