

Reference	SSM74315
Models	Discovery Sport / L550 Range Rover Evoque / L538 Range Rover Evoque / L551
Title	Coolant system level overfill - AJ20 Ingenium engines.
Category	Engine
Last modified	28-Feb-2019 00:00:00
Symptom	Cooling System Concerns
Content	<p>Issue: Retailers may report the coolant level is over the maximum fill line at PDI.</p> <p>Cause: Vehicles manufactured after 28/08/17 will arrive with a factory overfill condition.</p> <ul style="list-style-type: none">• This is intentional due to air being trapped during fluid fill in manufacturing.• The level will settle during the first year of service. <p>Action: No action is required if this condition is observed during PDI.</p> <ul style="list-style-type: none">• Do not remove any fluid.• During normal service and warranty repairs please continue to re-fill or top-up the coolant system as per TOPIx procedures.