



Preliminary Information

PIC6356 Normal Characteristic - Fuel Filler Door Does Not Lock

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Regal	2019	K1038582	EOP	All	All

Involved Region or Country	North America
Condition	A customer may comment that their fuel door does not lock. A vehicle enhancement was put into place which has eliminated the locking fuel filler door resulting in the door no longer locking.

Correction:

Do not replace any parts, the fuel door is operating as designed

Note: This PI may be converted into a bulletin when new information is available.

Version History

Version	1
Modified	03/13/2019 - Created



GENERAL MOTORS