



Preliminary Information

PIP5521B Malfunction Indicator Lamp MIL On DTC P0871 Or P2714 Set In The TCM

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Spark	2014 - 2019	All	All	All	M4M MR8

Involved Region or Country	North America
Condition	Some customers may comment on the operation or performance of the CVT7 transmission and/or the SES light is illuminated.
Cause	Technicians may find codes P0871 or P2714 set in the TCM.

Correction:

Dealers should now refer to bulletin [19-NA-053](#) for updated information regarding codes P0871 or P2714 set in the TCM.

Version History

Version	3
Modified	9/14/2017 - Created on 02/08/2019 - Updated to recommend transmission fluid pressure switch replacement instead of replacing the valve body and update model years. 03/20/2019 - Updated to refer dealers to bulletin 19-NA-053 for updated information regarding codes P0871 or P2714 set in the TCM.



GENERAL MOTORS