

# Latest Vehicle Concern Fixes



D7U Equipped with AJ126 Hesitation on Acceleration	18 – 19 RR, RRS, Discovery
<p><b>Customer Voice:</b></p> <ul style="list-style-type: none"><li>• There is a hesitation when accelerating from a stop or rolling stop</li><li>• The vehicle has a lag when pressing the gas then will jump and accelerate</li></ul> <p><b>Technical Description:</b></p> <ul style="list-style-type: none"><li>• The vehicles are operating to specification with a revised strategy for torque application</li></ul> <p><b>Status:</b></p> <ul style="list-style-type: none"><li>• The updated calibration has been removed from the tool for 14-17MY vehicles.</li><li>• A revised calibration is under development to address this complaint. The current target for release is April 2019.</li></ul>	<p><i>"Does not drive like previous Range Rovers did."</i></p> <p><i>"Gas pedal hesitates and vehicle does not accelerate"</i></p> <p><i>"No power pulling out, then will jerk while driving"</i></p> <p><i>"Hesitation upon acceleration. Feels like vehicle has no power."</i></p> <div data-bbox="1354 906 1921 1063"></div>

