

Latest Vehicle Concern Fixes



Battery Goes Flat due to Coolbox

18MY-19MY – Discovery/Range Rover/ RR Sport

Customer Voice:

- Intermittently flat battery complaint
- All terrain response switchpack LEDs flashing

Technical Description:

- Cool box sending CAN signal that prevents the All Terrain Control Module from going into sleep mode.

Status:

- SSM 74232 – Published on 1/16/2019.
 - Replace the Floor Console Cool Box refer to TOPIx workshop manual section 501-12A
- SSM will be updated with end VIN's for all affected models in the near future.

