



SERVICE BULLETIN

Classification: EC19-013	Reference: NTB19-021	Date: March 4, 2019
-----------------------------	-------------------------	------------------------

NISSAN; MIL ON WITH DTC P219A AND/OR P219B STORED

- APPLIED VEHICLES:**
- 2015-2018 Altima (L33)
 - 2019 Altima (L34)
 - 2017-2019 Armada (Y62)
 - 2015-2019 Frontier (D40)
 - 2015-2019 Murano (Z52)
 - 2016 Murano Hybrid (Z52)
 - 2015-2019 NV Cargo and Passenger (F80)
 - 2015-2019 Pathfinder (R52)
 - 2015-2019 Rogue (T32)
 - 2017-2019 Rogue Hybrid (T32)
 - 2015-2019 Sentra (B17)
 - 2017-2019 Titan (A61)
 - 2016-2019 Titan XD (A61) - VK56VD Gas engine
 - 2015-2019 Versa Note (E12)
 - 2016-2019 Versa Sedan (N17)

SERVICE INFORMATION

If the MIL is ON and DTC P219A (AIR FUEL RATIO IMBALANCE B1) and/or P219B (AIR FUEL RATIO IMBALANCE B2) is stored:

- **DO NOT replace the Air Fuel Ratio (A/F) sensor.**
- Refer to the applicable Electronic Service Manual (ESM) and follow the diagnostic procedure for DTC P219A and/or P219B.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
March 4, 2019	NTB19-021	Original bulletin published.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.