


LATEST VEHICLE CONCERN FIXES



Headlight Micro-cracking	F-TYPE 15 – 17 MY
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- A Customer may report the headlights have small cracks on the lenes <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- The micro-cracking is found on one and or both headlamp lenses on 15-17 MY F-TYPE. The issue is found concentrated above the headlamp beam on the clear part of the headlamp. <p><u>Status:</u></p> <ul style="list-style-type: none">- Currently Under Investigation- Raise an EPQR for any repairs performed and hold any parts replaced for return.	 A close-up photograph of a car's headlight assembly. The clear lens is the primary focus, showing several fine, hairline cracks that are most prominent in the upper portion of the lens, above the main projector beam. The surrounding housing is black plastic.

