



Technical Journal

TITLE:

Washer system layout for identifying leakage points

REF NO: TJ 25153.7.3	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2019-03-18	STATUS DATE: 2019-03-21
FUNC GROUP: 3634	FUNC DESC: Washer	Page 1 of 2	

“Right first time in Time”

Attachment

File Name	File Size
TJ 25153 S60 MY11-, V60, S60, V60CC.pdf	0.8349 MB
TJ 25153 S80 MY07-, V70 MY08-, XC70 MY08-.pdf	0.7857 MB
TJ 25153 S90(234) MY17-.pdf	1.4623 MB
TJ 25153 V90V90CC (235236) MY17-.pdf	1.5192 MB
TJ 25153 XC90(256) MY16-.pdf	2.1443 MB
TJ 25153_XC60.pdf	0.4566 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
124							2007-9999		0000850-9999999	200605-999952
134							2011-9999		0000194-9999999	201020-999952
135							2008-9999		0000395-9999999	200720-999952
136							2008-9999		0000400-9999999	200720-999952
138							2016-9999		0000122-9999999	201345-999952
155							2015-9999		0001147-9999999	201035-999952
156							2009-9999		0000212-9999999	200835-999952
157							2016-9999		0000022-9999999	201450-999952
234							2017-9999		0000001-9999999	201617-999952
235							2017-9999		0000001-9999999	201617-999952
236							2017-9999		0000001-9999999	201617-999952
256							2016-9999		0000001-9999999	201505-999952



CSC Customer Symptom Codes

Code	Description
1U	Washer fluid reservoir/hoses/Leakage

VST Operation Number

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

If leakage occurs in the washer system at any of the multiple connection locations, follow text under “Service”.

SERVICE:

In case of customer complaints regarding the washer system, inspect the complete washer system for leakages. Report the leaking connection number that you can find in attached layouts.

If possible, please add pictures of the concerned area/connection.

* For vehicle type 224, 225, 246, 536 and for future models the layout with connection numbers will be found in VIDA as a Product Fix Bulletin.

Information -> Bulletins -> Product Fix Bulletins -> 3 Electrical Systems -> 36 Other Electrical equipment -> 363 cleaner -> Washer system

IMPORTANT: Report the leaking connection number in both the Vehicle Report and in the repair order text of the warranty claim!

See Attachments:

[TJ 25153 S60 MY11-, V60, S60, V60CC](#)

[TJ 25153 S80 MY07-, V70 MY08-, XC70 MY08-](#)

[*TJ 25153_XC60](#)

[TJ 25153 XC90\(256\) MY16-](#)

[TJ 25153 S90\(234\) MY17-](#)

[TJ 25153 V90V90CC \(235236\) MY17-](#)

VEHICLE REPORT:

When submitting a Vehicle Report for a condition described in this TJ, use concern area “Vehicle Report and sub concern area “Support Not Needed” with function group 3634.

Due to the large number of attachments it will be necessary to view the attachments in TIE or www.volvotechinfo.com.