



Parts Bulletin

TITLE:

**Service Action S19854: Replace Engine Coolant (S60)
Model Year 2019 S60**

GROUP: 18	CAT/NO: S19854	REFERENCE BULLETINS: QB S19854	CAR MARKET: United States and Canada	
COPY TO / CIRCULATIONS (PLEASE INITIAL):			ISSUE DATE: 2019-02-26	STATUS DATE: 2019-02-26
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	
				Page 1 of 1

“Right first time in Time”

Reference Bulletins: QB S19854

Volvo Car USA LLC and Volvo Car Canada LTD (Volvo) on behalf of Volvo Car Corporation, has decided to launch Service Action S19854 on a **limited** number of model year 2019 S60 vehicles.

Volvo has identified that the engine coolant mixture is incorrect. The corrective action is to drain and fill with new coolant to a 50/50 ratio per VIDA instruction VCC-370342-12.

Service Action S19854 affects 39 vehicles in the U.S. and 5 in Canada.

RETAILER MUST CONFIRM VEHICLE ELIGIBILITY PRIOR TO BEGINNING THE REPAIR FOR THIS ACTION.

Vehicles in retailer inventory must be upgraded prior to sale.

PLEASE NOTE: Service Action S19854 will be in effect until June 30, 2021 regardless of mileage.

The following part number applies:

Part Number	Description	Qty
31439821	Coolant	1