

Technical Journal

TITLE:

Headlamp low/high beam malfunction, DTC HCM B157013 or B157913

REF NO: TJ 34547.1.0			CAR MARKET: United States and Canada		
3 US 7	PARTNER: '510 Volvo Car USA	ISSUE DATE: 2019-02-28	STATUS DATE: 2019-03-06		
FUNC GROUP: 3521	FUNC DESC: Headlamp, complete	Page	1 of 2		

"Right first time in Time"

Attachment

Vehicle Type

Туре	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
246						2019-2019	21	0291793-0309453	201846-201850

CSC Customer Symptom Codes

Code	Description			
YI	Active High Beam (AHB)/Does not work			
9T	Headlights/Vertical adjustment not influenced by steering wheel			
EY	Headlights/Does not work			
7G	Text window and warning symbol/Yellow symbol and text message			
IV	Text window and warning symbol/Text message			
CJ	Warning lights and chimes/Bulb failure indication/no indication			

VST Operation Number

VST Operation Number	Description
35203-2	Headlamp assembly x1 replace
35260-3	Headlamp control module (HCM) replace
36050-2	Calibrating/Identifying with VIDA

Technical Journal 34547.1.0



DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
HCMR	B157913	Intermittent
HCML	B157913	Intermittent
HCMR	B157913	Intermittent
HCML	B157013	Intermittent
HCMR	B157013	Intermittent

Text

DESCRIPTION:

- *ECU Electronic control module
- *HCMR Headlamp Control Module Right
- *HCML Headlamp Control Module Left

If DIM message "Low beam malfunction" or "High beam malfunction" and/or DTC HCM B157013 or HCM B157913 are set, follow advice under Service.

SERVICE:

Replace the faulty headlamp if the vehicle is inside the concerned chassis range in TJ header. Note: Do not replace the ECU HCML or HCMR. Do not replace both sides, only the one that is faulty.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3521.

Page 2 of 2 2019-03-06