



# Technical Service Bulletin

## 91 MIB2: Ignition on, the screen does not retract with the "Screen On/Off" button

91 19 53 2052238/2 April 12, 2019. Supersedes Technical Service Bulletin Group 91 number 18-09 dated August 24, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3, Q7	2018 - 2019	All	MIB2

## Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised title Revised <i>Production Solution</i> (Updated information)
1	08/24/2018	Initial publication

### Customer states:

- When the ignition is on the screen does not retract with the button "Screen On/Off" or with the MMI on/off button.



**Figure 1.** Screen On/Off button.

## Technical Background

Due to recent changes in regulation, the rear view camera has to be available within a certain timespan after the vehicle is put into reverse.

In order to facilitate this regulation, the screen cannot be lowered any more by the customer while the ignition is turned on.

## Production Solution

### Vehicles in the parked position:

MIB Last Mode "ON with opened Display"

- The display opens when the ignition is turned on
- MMI turns on



# Technical Service Bulletin

---

## MIB Last Mode “OFF”

- The display opens when the ignition is turned on
- MMI does NOT turn on
- Display remains black

## **While Driving:**

Pressing the display button

- Display turns black, remains in the opened position
- MMI remains on

Long press OFF

- Display turns black, remains in the opened position
- MMI turns off

## Service

The vehicle is functioning correctly.

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.

## Required Parts and Tools

A part replacement is not authorized.

## Additional Information

All parts and service references provided in this TSB (2052238) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes



# Technical Service Bulletin

---

at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.