



Technical Tip

Topic	57-18-01TT - Rear Lid Power Close Feature Inoperative with Key FOB
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	April 5, 2019

Condition

ATTENTION:
THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Rear Lid Power Close Feature Inoperative with Key FOB

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Tiguan LWB	2018-2019	All	All	All	All

Technical Background

Key FOB will not power close the rear lid.

Service

Verify that the vehicle does not have PR code 3KP, indicating 3rd row seating. The rear lid power assist will not operate with the key FOB, on vehicles with 3rd row seating.

Rear lid power assist will operate with the key FOB only on vehicles not equipped with 3rd row seating.



Tip:

The owner manual displays operation on vehicles with "5 seats".

Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2050488/2	4/5/19	Include additional model year applicability.
2050488/1	2/16/18	Original publication.

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.