

Subject: Engineering Information – Engine Oil Leak from Lower Oil Pan

This PI has been revised to end the need for information from the field. Please discard PIE0495.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2018	2018			Equipped with 2.0L, 2.5L Engines (RPOs LTG, LCV)	
	Regal						
Cadillac	ATS					Equipped with 2.0L, 2.5L Engines (RPOs LTG, LCV)	
	CT6					Equipped with 2.0L Engine (RPO LTG)	
	CTS					Equipped with 2.0L, 2.5L Engines (RPOs LTG, LCV)	
Chevrolet	Camaro					Equipped with 2.0L Engine (RPO LTG)	
	Colorado					Equipped with 2.5L Engine (RPO LCV)	
	Equinox					Equipped with 2.0L Engine (RPO LTG)	
	Impala					Equipped with 2.5L Engine (RPO LCV)	
	Malibu					Equipped with 2.0L (RPO LTG)	
	Traverse						
GMC	Acadia					Equipped with 2.5L Engine (RPO LCV)	
	Canyon						
	Terrain					Equipped with 2.0L (RPO LTG)	

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released November 05, 2018 March 15, 2019 – Ended the need for further information from the field.