

Subject: Engineering Information – Navigation SD Card Error Message OR USB Functionality Investigation

This PI has been revised to end the need for information from the field. Please discard PIE0502.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	LaCrosse	2019	2019				
	Regal						
Chevrolet	Colorado						
	Equinox						
	Silverado 1500 (New Model)						
GMC	Canyon						
	Terrain						
	Sierra 1500 (New Model)						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	March 15, 2019 – Ended the need for further information from the field.