
Reference	SSM74334
Models	Range Rover / L405 Range Rover Sport / L494
Title	HVAC software update causes Auxiliary Climate Control to stop producing cold air
Category	Electrical
Last modified	14-Mar-2019 00:00:00
Symptom	208000 Climate Control
Content	<p><u>Issue:</u> <i>HVAC software update causes Auxiliary Climate Control to stop producing cold air - rear refrigerant valve is not opened. Applicable to 18 MY and 19 MY vehicles only.</i></p> <p><u>Cause:</u> <i>HVAC software fault</i></p> <p><u>Action:</u> <i>Do not update the HVAC software. Note: this software is only required to support future vehicles, there is no customer benefit to update existing vehicles.</i></p> <p><i>This will be corrected in a future Pathfinder release.</i></p>